



U.S. Department
of Transportation

**Federal Aviation
Administration**


AFS-600

Regulatory Support Division

ADVISORY CIRCULAR

43-16A

AVIATION MAINTENANCE ALERTS



**ALERT
NUMBER
362**



**SEPTEMBER
2008**

CONTENTS

AIRPLANES

BEECH	1
CESSNA	11
LEAR	14

HELICOPTERS

BELL.....	15
-----------	----

AIR NOTES

INTERNET SERVICE DIFFICULTY REPORTING (iSDR) WEB SITE.....	15
IF YOU WANT TO CONTACT US	16
AVIATION SERVICE DIFFICULTY REPORTS	17

**U.S. DEPARTMENT OF TRANSPORTATION
FEDERAL AVIATION ADMINISTRATION
WASHINGTON, DC 20590**

AVIATION MAINTENANCE ALERTS

The Aviation Maintenance Alerts provides a common communication channel through which the aviation community can economically interchange service experience, cooperating in the improvement of aeronautical product durability, reliability, and safety. This publication is prepared from information submitted by those who operate and maintain civil aeronautical products. The contents include items that have been reported as significant, but have not been evaluated fully by the time the material went to press. As additional facts such as cause and corrective action are identified, the data will be published in subsequent issues of the Alerts. This procedure gives Alerts' readers prompt notice of conditions reported via a Malfunction or Defect Report (M or D) or a Service Difficulty Report (SDR). Your comments and suggestions for improvement are always welcome. Send to: FAA; ATTN: Aviation Data Systems Branch (AFS-620); P.O. Box 25082; Oklahoma City, OK 73125-5029.

(Editor's notes are provided for editorial clarification and enhancement within an article. They will always be recognized as italicized words bordered by parentheses.)



AIRPLANES

BEECH

Beech: C90; Cracked Drag Leg Support Brackets; ATA 5740

A repair station technician states, "The drag leg support brackets (*P/N 50-120077-16 & -17*) were found cracked on both left and right sides during a routine inspection. (*These*) cracks are most likely (*caused*) by fatigue or a rough landing."

Beechcraft
KING AIR C90, C90A & E90
ILLUSTRATED PARTS CATALOG





E90-63-7

57-16-00
PAGE 2

FIGURE 16-00.MAIN LANDING GEAR DRAG LEG SUPPORT
/SHEET 1 OF 2 SHEETS/

12/21/95






Part Total Time: 6, 171 hours.

Beech: 390; Distorted Nose Gear Stopper Assembly; ATA 3230

A technician describes an all too frequent problem for many airplanes. “The pilot reported (*having*) a ‘landing gear unlocked’ indication after selecting gear retraction (*subsequent to*) takeoff. We found the nose gear stopper assembly damaged, preventing the gear assembly from centering and (*properly*) engaging the uplock assembly. The stopper assembly was replaced after gear disassembly and inspection—gear operations then (*checked*) normal. It was reported this aircraft was previously towed with the nose gear torque links connected. The flight crew, ground operations personnel, and technicians should be aware of correct Premier towing procedures as specified in the 390 Maintenance Manual, section 9-10-01-201.” (*Stopper Assembly P/N: 390-820001-0001*)

Premier I/A Model 390 - Illustrated Parts Catalog
NOSE LANDING GEAR ASSY



32-20-10-01

2 OF 5

Page 2


Printed from IML Beechcraft Premier I/A Model 390 Revision 23 - August 2007
 P/N 390-590001-0011 Revision B1 - August 1, 2007


Part Total Time: 1,000.9 hours.

Beech: 400A; Sheared Rivets in Horz. Stab. Pivot Fitting; ATA 5510

(A repair station technician provides this and the next three 400A defect reports.)

“While performing a scheduled A-D inspection, eight sheared rivets were found in the forward rivet line of the attachment pivot fitting (P/N 45A21183-11) on the bottom of the horizontal stabilizer. It is suspected the missing rivets failed from fatigue. Recommendations are to inspect this area thoroughly at each inspection and to contact Hawker Beechcraft for repair options.” *(Horizontal stabilizer P/N 45A21002-41.)*





(Aircraft total cycles: 5,867. See similar defect further down. This particular N-numbered aircraft has an additional defect report—next.)


Part Total Time: 4,801.5 hours (aircraft time).

Beech: 400A; Blown Bleed Air Line Bellows; ATA 3010

(The previous aircraft has an additional defect report provided by the same technician. His efforts at photographic documentation were quite thorough—more than enough is presented here to make the scary point!)

Our technician states, “While performing a scheduled A-D inspection, the left aft fuselage bleed air line bellows (P/N 45A63517-073) was found blown apart. The right aft fuselage bleed air line bellows-braiding (P/N 45A63517-075) was found fraying. When the left bleed air line blew apart it cracked a fuselage bulkhead at upper frame station 329.92 and BP 29.92L. I would recommend that detailed inspections of these bleed air lines be performed at scheduled intervals, and the upper frame station in the areas around the bleed air lines be carefully inspected for damage. It is suspected both bleed lines failed due to fatigue or time in service.






(Aircraft total time: 4,801.5 hours.)

Part Total Time: (unknown).

Beech: 400A; Sheared Rivets in Horz. Stab. Pivot Fitting; ATA 5510

(The above repair station technician continues here with more sheared horizontal stabilizer rivets found on another 400A.)

“While performing a scheduled A-D inspection, six sheared rivets and two loose rivets were found in the forward rivet line of the attachment pivot fitting (P/N 45A21183-11) on the bottom of the horizontal stabilizer. It is suspected the missing rivets failed from fatigue. Recommendations are to inspect this area thoroughly at each inspection and to contact Hawker Beechcraft for repair options. This is the second aircraft this same discrepancy has been found.”



(Horizontal stabilizer P/N 45A21002-91; note this number slightly different from the previous stabilizer number. Aircraft total cycles: 4,331.)

Part Total Time: 4,730.0 hours *(aircraft total time)*.

Beech: 400A; Cracked Copilots Side Window; ATA 5610

(This is the last of four discrepancies from the previous submitter for his two Beechjet 400A's. This entry continues the previous aircraft's inspection.)

“While performing a scheduled A-D inspection, I found the copilot’s cockpit side window cracked using the prism inspection method. The ‘D’ inspection requires both windshields be inspected by removing the windshield retainers or using optical prism inspection (*criteria*). There is no statement in the aircraft or in the A-D inspection checklist that requires one to inspect the cockpit side windows in the same manner as the windshields. All of the windows in the cockpit area are installed or fastened in the same manner as the windshields. It is suspected the copilot side window cracked from fatigue, or total time installed. This window was manufactured in May of 1997. It is recommended inspections of all cockpit windows with a prism be completed at scheduled intervals.”



(Copilot side window P/N 45AS31010-12. Aircraft total cycles: 4,331; aircraft total time: 4,730.0 hours. Good advice, sir. Thank-you for your efforts and detailed photographs—Ed.)

Part Total Time: (unknown).

CESSNA

Cessna: 172RG; Cracked Main Gear Actuator; ATA 3233

A licensed aircraft mechanic states, “The pilot reported a loud ‘pop’ just before entering the pattern. When he extended the gear, the green ‘gear down’ light would not come on. A fly-by revealed the left gear was in transit. A gear-up landing followed.

“Inspection of the left main gear actuator (P/N 9882015-2) revealed the actuator housing was cracked across the forward attach bolt hole. The cracked housing allowed the piston rack to jump gears on the pinion gear attached to the main gear leg. This area is inspected each 100 hours for cracks and defects very carefully, *(using)* lights and inspection mirrors. *(Elapsed...)* time since the last inspection: 25.0 hours. (AD 2001-06-06 was complied with in 2001 with 4,516 hours and no defects found.)”

(A search of the FAA Service Difficulty Reporting System data base for this actuator P/N revealed at least 39 similar entries.)

Part Total Time: 6,917.0 hours.


Cessna: 172/180/185; (all models); Control Yoke Corrosion; ATA 2701

(This safety article applies to the above series aircraft built from 1964 through 1985. It is published as received from the Wichita Aircraft Certification Office, including contact information found at discussion's end.)

"The FAA recently proposed in a safety recommendation to issue an Airworthiness Directive to comply with Cessna SEB01-3R1. The purpose for this service bulletin is given as follows: 'Reports have been received of some control yokes corroding internally resulting in failure of the control yoke below the pivot attach point. The control yoke shall be inspected, and if required, replaced as described in this service bulletin. Non-compliance with this service bulletin may result in failure of the control yoke which could cause complete loss of elevator control.'

"The safety recommendation was issued because of a reported failure of a control yoke that was found while complying with the service bulletin on a 1985 Cessna 172P in Anchorage, Alaska during April 2008. As shown in the photograph, the drain hole appears to be larger than ¼ inch diameter and is mislocated. The correct position is shown in the enclosed Figure 1 from page 11 of SEB01-3R1. The FAA has determined that this alteration from the service bulletin weakened the tube structure, and may have contributed to the failure.

"For additional information on maintaining the control yokes, we suggest that you review the FAA Special Airworthiness Information Bulletin (SAIB) CE-04-03, Cessna Service Bulletin SEB01-3R1, and the article published in the Cessna Pilot Association (CPA) in September 2002 on pages 6308 through 6311 entitled 'CPA Comments to the Airworthiness Concern Sheet dated 5/31/02'."







Figure 1. Control Yoke Inspection



(For more information contact Aerospace Engineer Gary Park, Wichita Aircraft Certification Office, 1801 Airport Road, Room 100, Wichita, Kansas, 67209-1985. Phone 316-946-4123.)

Part Total Time: (n/a).

LEAR

Lear: 45; Improper Teleforce Cable Routing; ATA 7603

A technician for a repair station states, "An inspection through the access panel in the L/H wheel well revealed the L/H thrust lever teleforce (*cable*) was fully in contact (*along most of its length*) with the L/H rudder cable— (*creating high potential for chafing damage*). Further inspection showed the Teleforce cable was not routed properly and not (*positioned correctly*) in the Teflon holder." (*No part numbers were provided with this report.*)

Part Total Time: (unknown).

HELICOPTERS

BELL

Bell: 206BIII; Locked, Cyclic Servo Hydraulic Actuator; ATA 6730

(The following defect description is provided by Aviation Safety Inspector Gregory J. Mihalyak from the Philadelphia Flight Standards District Office. Contact information is found at the article's end.)

“During a quick, turn-around flight last July, a 206BIII flight crew noted the cyclic control stick could not be moved when the *hydraulic system switch* was placed in the ‘off’ position (reference the ‘After Start: Preliminary Hydraulics Check’ procedure). The pilot also noted the cyclic and flight controls responded normally when the *hydraulic system switch* was returned to the ‘on’ position. The aircraft was shutdown and inspected by maintenance personnel. Subsequent troubleshooting with auxiliary hydraulic power produced normal hydraulic system operation. Flight crew personnel again attempted to duplicate the problem during normal operation. The aircraft was repeatedly flown in five minute hovers and then set down. Upon each landing the *hydraulic system switch* was turned ‘on’ and ‘off.’ After performing these actions several times the cyclic control was again found to be *locked*—duplicating the original discrepancy. It was determined the R/H cyclic servo actuator (P/N 206-076-031-107) was locking-up when the *hydraulic system switch* was selected ‘off.’ As a precaution, the similar L/H servo was also replaced, eliminating the possibility it too might be contributing to the problem.

“The Rotorcraft Flight Manual (RFM) requires the flight controls be tested twice before each flight: once during the System Check *after* the engine has been started, and a second time during engine run-up. The quick turn-around nature of the original mission allowed this flight control/hydraulic test to be performed by the crew at an opportune time: the hydraulic fluid remained at or was near normal operating temperatures. This unique event is what led to the discovery of the malfunctioning servo. Normal testing—as required in the RFM—did not reveal this condition.”

(For further information contact Inspector Gregory Mihalyak; Philadelphia Flight Standards District Office 17, 2 International Plaza Suite 110, Philadelphia, PA. 19113; phone 610-595-1500 ext. 241.)

Part Total Time: (unknown).

AIR NOTES

INTERNET SERVICE DIFFICULTY REPORTING (iSDR) WEB SITE

The Federal Aviation Administration (FAA) Internet Service Difficulty Reporting (iSDR) web site is the front-end for the Service Difficulty Reporting System (SDRS) data base that is maintained by the Aviation Data Systems Branch, AFS-620, in Oklahoma City, Oklahoma. The iSDR web site supports the Flight Standards Service (AFS), Service Difficulty Program by providing the aviation community with a voluntary and electronic means to conveniently submit in-service reports of failures, malfunctions, or defects on aeronautical products. The objective of the Service Difficulty Program is to achieve prompt correction of conditions adversely affecting continued airworthiness of aeronautical products. To accomplish this, Malfunction or Defect Reports (M or Ds) or Service Difficulty Reports (SDRs) as they are commonly called, are collected, converted into a common SDR format, stored, and made available to the appropriate segments of the FAA, the aviation community, and the general public for review and analysis. SDR data is accessible through the “Query SDR data” feature on the iSDR web site at: <http://av-info.faa.gov/sdrx/>.

In the past, the last two pages of the Alerts contained a paper copy of FAA Form 8010-4, Malfunction or Defect Report. To meet the requirements of *Section 508, this form will no longer be published in the Alerts; however, the form is available on the Internet at: <http://forms.faa.gov/forms/faa8010-4.pdf>. You can still download and complete the form as you have in the past.

*Section 508 was enacted to eliminate barriers in information technology, to make available new opportunities for people with disabilities, and to encourage development of technologies that will help achieve these goals.

A report should be filed whenever a system, component, or part of an aircraft, powerplant, propeller, or appliance fails to function in a normal or usual manner. In addition, if a system, component, or part of an aircraft, powerplant, propeller, or appliance has a flaw or imperfection, which impairs or may impair its future function, it is considered defective and should be reported under the Service Difficulty Program.

The collection, collation, analysis of data, and the rapid dissemination of mechanical discrepancies, alerts, and trend information to the appropriate segments of the FAA and the aviation community provides an effective and economical method of ensuring future aviation safety.

The FAA analyzes SDR data for safety implications and reviews the data to identify possible trends that may not be apparent regionally or to individual operators. As a result, the FAA may disseminate safety information to a particular section of the aviation community. The FAA also may adopt new regulations or issue airworthiness directives (ADs) to address a specific problem.

The iSDR web site provides an electronic means for the general aviation community to voluntarily submit reports, and may serve as an alternative means for operators and air agencies to comply with the reporting requirements of 14 Title of the Code of Federal Regulations (CFR) Section 121.703, 125.409, 135.415, and 145.221, if accepted by their certificate-holding district office. FAA Aviation Safety Inspectors may also report service difficulty information when they conduct routine aircraft maintenance surveillance as well as accident and incident investigations.

The SDRS data base contains records dating back to 1974. At the current time, we are receiving approximately 40,000 records per year. Reports may be submitted to the iSDR web site on active data entry form or submitted hardcopy to the address below.

The SDRS and iSDR web site point of contact is:

Pennie Thompson
Service Difficulty Reporting System, Program Manager
Aviation Data Systems Branch, AFS-620
P.O. Box 25082
Oklahoma City, OK 73125
Telephone: (405) 954-1150
SDRS Program Manager e-mail address: 9-AMC-SDR-ProgMgr@faa.gov

IF YOU WANT TO CONTACT US

We welcome your comments, suggestions, and questions. You may use any of the following means of communication to submit reports concerning aviation-related occurrences.

Editor: Daniel Roller (405) 954-3646
FAX: (405) 954-4570 or (405) 954-4655

E-mail address: Daniel.Roller@faa.gov

Mailing address: FAA, **ATTN: AFS-620 ALERTS**, P.O. Box 25082, Oklahoma City, OK 73125-5029

You can access current and back issues of this publication from the internet at:
<http://av-info.faa.gov/>. Select the General Aviation Airworthiness Alerts heading.

AVIATION SERVICE DIFFICULTY REPORTS

The following are abbreviated reports processed for the previous month, which have been entered into the FAA Service Difficulty Reporting (SDR) System data base. This is not an all-inclusive listing of Service Difficulty Reports. For more information, contact the FAA, Regulatory Support Division, Aviation Data Systems Branch, AFS-620, located in Oklahoma City, Oklahoma. The mailing address is:

FAA
Aviation Data Systems Branch, AFS-620
PO Box 25082
Oklahoma City, OK 73125

To retrieve the complete report, click on the Control Number located in each report. These reports contain raw data that has not been edited. Also, because these reports contain raw data, the pages containing the raw data are not numbered.

If you require further detail please contact AFS-620 at the address above.

Federal Aviation Administration

Service Difficulty Report Data

Sorted by aircraft make and model, then engine make and model. This report derives from unverified information submitted by the aviation community without FAA review for accuracy. To view individual report go to the SDR query page and enter the control number of the record you wish to view: <http://av-info.faa.gov/sdrx/query.aspx>

Control Number Difficulty Date	Aircraft Make Aircraft Model	Engine Make Engine Model	Component Make Component Model	Part Name Part Number	Part Condition Part Location
COEA0802821	AEROSP			WARNING SYSTEM	MALFUNCTIONED
7/15/2008	ATR72202				NLG
RETURN TO FIELD. FLIGHT 100 GEG TO GEG. THE NOSE WHEEL UNLOCK LIGHT ILLUMINATED IMMEDIATELY UPON ROTATION ALONG WITH THE NOSE GEAR DOWN AND LOCKED LIGHT REMAINING ILLUMINATED. AFTER THE LANDING GEAR HANDLE WAS SELECTED "UP", BOTH MAINS RETRACTED NORMALLY. THE NOSE GEAR DID NOT RETRACT AND THE DOUBLE INDICATION CONTINUED SHOWING BOTH NOSE GEAR LOCKED AND UNLOCKED. THE CREW ELECTED TO RETURN TO GEG FOR LANDING. THE LANDING GEAR WAS SELECTED "DOWN" GIVING ALL SIX NORMAL GEAR DOWN INDICATIONS AFTER GEAR EXTENSION. A NORMAL AND SAFE LANDING WAS MADE. THE NOSE LANDING GEAR STRUT WAS SERVICED AND A LANDING GEAR FUNCTION CHECK WAS PERFORMED. THE LANDING GEAR CHECK FOUND NO SYSTEM FAULTS. (A)					
COEA0804816	AEROSP			BULKHEAD	NICKED
8/5/2008	ATR72212			S53174000200	FUSELAGE
TOOL DAMAGE TO FWD SIDE OF FWD PRESSURE BULKHEAD. THREE SMALL NICKS FOUND AT THE LT UPPER RADOME BONDING CONTACT POINT. S/D HC AT COE. S/D SRM REPAIR, BLENDED OUT DAMAGE AND INSTALLED REPAIR DOUBLER TO THE BULKHEAD WEB. (S)					
COEA0805816	AEROSP			PANEL	CORRODED
8/6/2008	ATR72212			S5241055700000A	CENTER WING
LEVEL 2 CORROSION. SURFACE CORROSION ON MATTING SURFACE OF PANEL 521DT. BLENDOUT OF CORROSION BLENDED BEYOND SRM LIMITS. S/D HC AT COE. REMOVED AND REPLACED DRY BAY ACCESS PANEL 521DT. (S)					
2008FA0000562	BEECH	PWA		FRAME	CRACKED
6/27/2008	1900D	PT6*		12943003723	FS 363.25
DURING STRUCTURAL INSP, FOUND LOWER FRAME WEB CRACKED AT FLANGE CORNER. TEE ATTACHED TO FRAME CRACKED THRU LOWER RIVET HOLE. DOUBLER ATTACHED TO LOWER AFT SIDE OF WEB WAS ALSO CRACKED. THE AFT CLIP, ATHAT ATTACHES THE LOWER FRAME TO THE SIDEWALL SEAT TRACK STRINGER, WAS LEFT OUT AT BUILD. THE STRESSES NOT BEING TRANSFERRED TO SUPPORTING STRUCTURE, BECAUSE OF THE MISSING CLIP, MAY HAVE ADDED TO THE FRAME FAILURE. THE DAMAGE WAS REPAIRED IAW SRM AND DER REPORT. (K)					
DJFA2008051	BEECH			INTAKE	CRACKED
6/4/2008	400A			45A35022601	LT ENGINE
DURING ROUTINE MAINTENANCE THE LT INLET SKIN AT THE INLET TEMPERATURE PROBE WAS FOUND CRACKED. THE LT INLET WAS REPLACED. (A)					
DJFA2008062	BEECH			CABIN PRESSURE	FAILED
7/6/2008	400A				
TEMPORARILY LOST PRESSURIZATION AT FL300. OXYGEN MASKS DROPPED. EMERGENCY WAS DECLARED. AIRCRAFT LANDED SAFELY. (A)					
DJFA2008056	BEECH			SKIN	CRACKED
6/19/2008	400A				LT ENG INTAKE
DURING A ROUTINE SERVICE CHECK IT WAS NOTED THAT THE LT ENGINE INLET INNER SKIN WAS CRACKED AT THE 9 O'CLOCK POSITION. THE INLET WAS REMOVED, REPAIRED BY INTEGRITY AERO AND REINSTALLED. (A)					
2008FA0000540	BEECH	PWA		WHEEL	CRACKED

5/2/2008	B200	PT6*	4088	MLG
CRACK INDICATIONS LOCATED IN BEAD AREA OF WHEELS, REVEALED BY FLUORESCENT PENETRANT. (K)				
2008FA0000563	BEECH	PWA	FUEL CELL	PLUGGED
8/8/2008	B300	PT6A60A	5038903417	LT WING
PILOT REPORTED FUEL IMBALANCE OF 200 LBS AFTER TOPPING OFF TANKS. FUEL QUANTITY INDICATING AND FUEL VENT SYSTEM WERE CHECKED AND CONFIRMED GOOD. DURING DEFUEL, NOTED THAT LT WING TRANSFER TO LT NACELLE TANK WAS TOO SLOW TO ALLOW FULL SERVICING OF LT WING FUEL SYSTEM. ACCESSED FUEL TRANSFER TUBE FROM INSIDE OF LT IB AFT FUEL CELL, TO NACELLE FUEL TANK, AND FOUND IT PLUGGED WITH A RAG. REMOVED RAG, CLEANED WING FUEL STRAINER, AND SECURED FUEL SYSTEM. LT FUEL SYSTEM CAN NOW BE SERVICED TO FULL. (K)				
2008FA0000543	BELL		HUB	CRACKED
7/28/2008	47G		471201171	MAIN ROTOR
BEAM - CRACK INDICATION AT EAR END (FPT). HUB - CRACK INDICATIONS AT RADIUS ON STUB ENDS. (K)				
2008FA0000542	BELL		BEAM	CRACKED
7/28/2008	47G		471201281	MAIN ROTOR
BEAM CRACK INDICATION AT EAR END (FPT). HUB - CRACK INDICATIONS AT RADIUS ON STUB ENDS (FMT). (K)				
PL92008F00000	BOEING	PWA	TURBINE BLADES	FAILED
8/16/2008	707330B	JT3D3B	J53D3B	TURBINE WHEEL
DURING CLIMBOUT FROM PHX NR 4 ENG EGT BEGAN TO CLIMB RAPIDLY AND NR 1 & NR 2 SPOOLED DOWN. ENG WAS SHUT DOWN FOLLOWING PUBLISHED PROCEDURES AND THE ACFT RETURNED TO PHX AND LANDED WITHOUT INCIDENT. AFTER LANDING THE ENG WAS INSPECTED AND FOUND THAT THERE WERE SEVERAL SECTIONS OF TURBINE BLADES HAD FAILED AND CAUSED ADDITIONAL DAMAGE TO THE TURBINE WHEELS AFT OF THE FAILED DISC BLADES. THE DAMAGE WAS CONTAINED WITHIN THE TAIL PIPE AND NO EXTERNAL DAMAGE WAS NOTED TO ANY ADJACENT AREAS. (S)				
MWE2008F00030	BOEING		STATIC INVERTER	INOPERATIVE
8/10/2008	717200		100201020752	
DURING INITIAL POWER UP OF AC, WHEN SELECTING EMERGENCY POWER TO ARM "BUSS AC EMERGENCY OFF" COMES ON AND BATTERY STARTS DISCHARGE. REMOVED AND REPLACED STATIC INVERTER. (K)				
MWE2008F00031	BOEING	RROYCE	BATTERY PACK	INOPERATIVE
8/14/2008	717200	BR700715A130	6011779	EMERGENCY LIGHT
CEILING LIGHTS FWD OF THE CABIN DID NOT ILLUMINATE. REMOVED AND REPLACED BATTERY PACK. (K)				
MWE2008F00033	BOEING	RROYCE	RELAY	FAILED
8/17/2008	717200	BR700715A130	R25159	EMERGENCY POWER
EMERGENCY POWER TEST FAILED. SHOWS NO POWER TO EMERGENCY AC. REMOVED AND REPLACED EMERGENCY POWER RELAY. (K)				
TSAA0826023	BOEING		WARNING LIGHT	FALSE ACTIVATION
7/25/2008	737*			OVERHEAT
FLT 320, HNL-OAK: LT WING-BODY OVERHEAT LIGHT ILLUMINATED IN FLIGHT DURING CRUISE AT ABOUT FL350. LIGHT WENT OUT AFTER. ACCOMPLISHED QRH PROCEDURES AND RETURNED TO HNL. INSPECTED AIR CONDITIONING BAY DUCTS, LEADING FLAP DUCTS AND OVERWING DUCTS. NO LEAKS DETECTED. ALSO PERFORMED HIGH POWER RUN; SYSTEM CHECK GOOD. AIRCRAFT RETURNED TO SERVICE. (A)				
2008UALA04056	BOEING	CFMINT	CONTROL PANEL	ILLUMINATED
7/28/2008	737322	CFM563C1	G718505	FIRE DETECTION
FAIL LIGHT ILLUMINATED ON B-LOOP AFT CARGO COMPARTMENT. FOUND CONTROL PANEL TO BE FAULTY. REPLACED CONTROL PANEL CARGO FIRE DETECTION AND SUPPRESSION REF 26-00-02 OP CHECKS GOOD. AC OK FOR SERVICE.				
BJN2008F00000	BOEING		LAMP	BURNED OUT
8/15/2008	737400		1317	EMERGENCY LIGHT

ONE EMERGENCY AISLE LIGHT, ROW 12, RT SIDE, BURNED OUT. REPLACED EMERGENCY LIGHT BULB. (K)

AIEA200800256	BOEING	GE	FIRE DETECTOR	DIRTY
7/7/2008	747243B	CF650E2		CARGO BAY
RETURN TO BLOCKS INTERMITTENT FIRE WARNING DURING TAXI. FOUND EVIDENCE OF DE-GERM IN CARGO SNIFFED TUBE. CLEANED SNUFFER TUBES WITH CONTACT CLEANER. SYSTEM OPS CHECK NORMAL AS PER MM 26-16-00. (A)				
AIEA200800257	BOEING	GE	FRAME	CRACKED
7/7/2008	747243B	CF650E2		BS 280 S26R
DURING C-CHECK FOUND FRAME CRACKED AT STATION 280 STRINGER 26R. FRAME REPAIRED AS PER SRM 53-10-04 FIGURE 10. (A)				
AIEA200800259	BOEING	GE	FRAME	CRACKED
7/7/2008	747243B	CF650E2		BS 320 S25R
DURING C-CHECK FOUND FRAME CRACKED AT STATION 320 STRINGER 25R. FRAME REPAIRED AS PER SRM 53-10-04 FIGURE 10. (A)				
AIEA200800258	BOEING	GE	FRAME	CRACKED
7/7/2008	747243B	CF650E2		BS 280 S26L
DURING C-CHECK FOUND FRAME CRACKED AT STATION 280 STRINGER 26L. FRAME REPAIRED AS PER SRM 53-10-04 FIGURE 10. (A)				
AIEA200800262	BOEING		TIRE	FAILED
7/8/2008	74747UF			RT MLG
DURING ARRIVAL WALK AROUND INSPECTION FOUND NR 11 TIRE SEPARATION. REPLACED NR 11 AND 12 WHEEL ASSEMBLIES. ALSO ACCOMPLISHED TIRE TREAD LOSS CONDITIONAL INSPECTION AS PER 05-51-34-202-001. (A)				
AIEA200800263	BOEING		FAIRING	DAMAGED
7/8/2008	74747UF			FUSELAGE
DURING ARRIVAL WALKAROUND INSPECTION FOUND LOWER RT AFT OF BODY GEAR FUSELAGE FAIRING DAMAGED. ACCOMPLISHED TIME LIMITED REPAIR AS PER EO 4453A188 DATED 7/8/08 ENTERED NON MEL DMI N08-037 FOR REPEAT INSPECTION OF PANEL AT EVERY A-CHECK. (A)				
AIEA200800260	BOEING	GE	ENGINE	OIL CONSUMPTION
7/7/2008	74747UF	CF680		NR 3
ENGINE NR 3 OIL QTY WENT TO 0 (3 HOURS AFTER TAKEOFF). ENGINE SHUT DOWN PRECAUTIONARY. FIM 79-00-00 FOLLOWED. INSPECTED FOR OIL LEAK. NO WETTING FOUND. REPLENISHED 22 QTS OIL AND LEAK AND OPS CHECK PERFORMED. NO LEAK FOUND. IDG AND STARTER DRAIN LINE CAPPED FOR MONITORING PER AMM 71-71-00. (A)				
ABXR080225	BOEING		SKIN	DAMAGED
7/29/2008	767223			BS 615 S34R
SCREW AND COUNTERSINK WASHER INSTALLED IN FUSELAGE SKIN OVER PREVIOUSLY BLENDED AREA AT APPROX STA 615 LONGERON STRINGER 34 RT. DAMAGED AREA COMPLIED WITH ON PREVIOUS REPAIR. (S)				
ABXR080228	BOEING		SKIN	DENTED
8/1/2008	767223		143T35211	BS 544 S30-31L
OUTWARD DENT STA 544, STRINGER 31-30 LT REQUIRES REPAIR. REPAIRED AREA IAW B767 SRM 53-00-01, FIGURE 201. (S)				
ABXR080226	BOEING		SKIN	DAMAGED
7/31/2008	767223		146T35111	BS 1510 S35-36L
APPROX 6 INCH CREASE AT STA 1510, LONGERON STRINGER 36-35 LT, BELOW BULK CARGO DOOR IS OUT OF LIMITS. REPAIRED SKIN IAW B767-200 SRM 53-60-1. (S)				
ABXA080224	BOEING		LONGERON	CRACKED
8/7/2008	767232		148T9120	EMPENNAGE

UPPER LONGERON ABOVE HORIZONTAL BOX WEB CRACKED AND DAMAGED STA 1734 LT SIDE. REPAIRED IAW REA B653-57691. (S)

ABXA080221	BOEING	SKIN	CRACKED
8/1/2008	767232	148T31311	BS 1654 S13L

LT STA 1654.5, 2 EACH SKIN CRACKS STRINGER 13 LT. REPAIRED LT STA 1654.5 AT STRINGER 13 LT ON REA B653-57700. (S)

ABXA080223	BOEING	SKIN	CRACKED
8/5/2008	767232	114T0222	LT TRACK CUTOUT

FOUND CRACK AT NR 3 SLAT OUTBOARD TRACK CUTOUT ON LEADING EDGE OF LT WING. REPAIRED SPLICE PLATE IAW REA B65757685. (S)

ABXA080212	BOEING	WEB	CORRODED
7/15/2008	767281	143T500418	BS 624

WEB CORRODED ON BOTTOM SIDE AT FS 624 AT RIGHT BUTT LINE 38.5. REMOVED AND REPLACED CORRODED WEB IAW B767 SRM. (A)

ABXA080209	BOEING	SEAT TRACK	CORRODED
7/10/2008	767281		BS 412-423

SEAT TRACK CORRODED LT BUTT LINE 13.28, STA 412-423. REMOVED AND REPLACED SEAT TRACK IAW B767-200 SRM 51-40-2. (A)

EYD2008F00001	BRAERO	CONTROLLER	MALFUNCTIONED
8/6/2008	HS125700A	10246429	CABIN PRESSURE

ON AUGUST 6TH, WHILE EN ROUTE AT AN ALTITUDE OF 35,000 FEET, THE CREW EXECUTED AN EMERGENCY DESCENT DUE TO A "CABIN ALTITUDE" LIGHT. THE CREW CONTINUED ON TO FXE UNEVENTFULLY. AFTER TROUBLESHOOTING THE PRESSURIZATION SYSTEM, IT WAS DETERMINED THAT THE PRESSURIZATION CONTROLLER P/N 10-1443, THAT HAD BEEN INSTALLED IN OVERHAULED CONDITION THE PREVIOUS WEEK, HAD FAILED. THE CONTROLLER WAS REPLACED AND THE SYSTEM IS WORKING NORMALLY. (S)

2008FA0000558	CESSNA	FITTING	CORRODED
8/1/2008	140	0425118	LT TE FLAP

THE PART WAS BEGINNING TO RUST THROUGH IN LOCATION RESPONSIBLE FOR ATTACHING THE LT FLAP TO THE FLAP CONTROL. THE DEFECT WAS FOUND DURING AN ANNUAL INSPECTION. PROBABLE CAUSE WAS RUSTING DUE TO AGE. A MORE THOROUGH INSPECTION OF THE AREA DURING PREFLIGHT SHOULD HELP DETECT THE PROBLEM SO THAT CORRECTIVE ACTION CAN BE TAKEN.

2008FA0000574	CESSNA	CONT	IMPULSE COUPLING	FAILED
8/15/2008	182N	O470R		MAGNETO

PILOT PERFORMED PRE-FLIGHT INSP DISCOVERED OIL ON FWD PORTION OF COWLING, SLIGHT OIL RESIDUE ON WINDSHIELD. MECHANIC REMOVED TOP COWLING TO INVESTIGATE, DISCOVERED MAGNETO HOUSING SHATTERED AT AREA IMMEDIATELY ADJACENT TO IMPULSE COUPLING. APPARENTLY IMPULSE COUPLING ENGAGING MECHANISM SOMEHOW CONTACTED ACTUATING PIN WHILE OPERATING (OR ENGINE BACKFIRED, WE DON'T HAVE FURTHER INFORMATION TO ASCERTAIN THIS CONDITION) SHATTERED MAGNETO BODY HSG. MAGNETO WAS STILL FIRING, FIXED TO ENGINE (NOT LOOSE) ENGINE OPS WAS REPORTED NORMAL UPON ARRIVAL OF LAST FLIGHT, WHICH SEEMS TO INDICATE THAT MAGNETO HAD OPERATED IN THIS CONDITION FOR WHAT APPEARS TO BE AT LEAST AN HOUR OR MORE. NO MISFIRE OR MAGNETO DROP DETECTED.

COEA0801775	CESSNA	TIRE	FAILED
7/28/2008	208B	0253490	RT MLG

TIRE WENT FLAT AFTER LANDING, FLT 7689 SLE TO PDX. UPON LANDING IN PDX THE PILOT NOTICE THE RT MLG TIRE FELT SOFT. AS THE AIRCRAFT SLOWED THE TIRE WENT FLAT. AIRCRAFT SAFELY CLEARED RUNWAY AND STOPPED. REMOVED AND REPLACED RT MAIN WHEEL ASSEMBLY. (A)

COEA0801752	CESSNA	GYRO	FAILED
7/19/2008	208B	0600001700	LT INSTR PANEL

RETURN TO BLOCKS. THE PILOT'S SIDE ATTITUDE INDICATOR WILL NOT ERECT. DISCOVERED DURING TAXI TO THE RUNWAY. REMOVED AND REPLACED, ARTIFICIAL HORIZON. (A)

FPI2008F00000	CESSNA	CONT	CABLE	BROKEN
8/21/2008	210M	IO520*	505530401	UNKNOWN
MFG SERVICE KIT PN SK210174, CABLE ASSY BROKE AT THREADED END AFTER THE STOP NUT SEVEN WEEKS AFTER INSTALLATION APPEARS THREAD WALL IS TOO THIN LEADING TO FATIGUE. (K)				
XGN2008F00012	CESSNA	CONT	CYLINDER	CRACKED
8/1/2008	402B	TSIO520*	AEC631397	ENGINE
REV 3, E=SERIES CYLINDER, CRACKED. (K)				
PI82008F00000	CESSNA	CONT	TURBOCHARGER	FAILED
7/18/2008	402B	TSIO520E	4066109025	RT ENGINE
TURBOCHARGER FAILED IN FLIGHT AT CRUISE. (A)				
YBS2008F00000	CESSNA	CONT	SELECTOR VALVE	DAMAGED
7/11/2008	402C	TSIO520*	9102011	LT WING FUEL
AT CLIMB POWER-RT FUEL FLOW DROPPED TO 90 PPH. AUX PUMP ON LOW FIXED PROBLEM TEMPORARILY. FUEL FLOW DROPPED AGAIN AND LT ENGINE SURGE. RETURNED TO DEPARTURE AIRPORT AND LANDING WITHOUT INCIDENT. MX REMOVED AND REPLACED LT FUEL SELECTOR VALVE. ALSO REPLACED AUX FUEL PUMP AND CROSSFEED VALVE AS A PRECAUTIONARY MEASURE. (A)				
26N2008F00002	CESSNA	PWC	CONTROL CABLE	FROZEN
8/4/2008	510	PW615FA	70611107	ELEVATOR
7/24/2008, AC TT: 461.8, TC:302 CREW REPORTED AILERONS FROZEN AFTER FLYING THROUGH MOISTURE (FROM FORM 26NA-210A, ATTACHED) 7/25/2008, AC REPOSITIONED TO MFG SERVICE CENTER FOR FURTHER EVALUATION AND RESOLUTION. 8/1/2008, AC TT: 462.3 MFG MTR FOR RESOLUTION. (K)				
842008N341CS	CESSNA		BRAKE	CONTAMINATED
7/30/2008	550			MLG
THE LOW BRAKE PRESSURE AND ANTI-SKID INOP ANNUNCIATORS ILLUMINATED IN FLIGHT. AN EMERGENCY WAS DECLARED. DURING LANDING ROLL OUT BRAKE PRESSURE CAME BACK AND LIGHTS EXTINGUISHED. THE BRAKES WERE BLED, A SMALL AMOUNT OF AIR NOTED. OPERATIONAL CHECK OK. ACFT MADE THREE TAKEOFFS AND LANDINGS WITH NO DEFECTS NOTED. ACFT RETURNED TO SERVICE. (S)				
2008FA0000584	CESSNA		SEAT FRAME	CRACKED
7/31/2008	550		551900921	COCKPIT SEAT
UPPER CHAIR BASE ASSY CRACKED AT CHAIR BACK ATTACH POINTS. STRESS ON CHAIR BACK AND METAL FATIGUE PROBABLE CAUSE. CHAIR WAS REPAIRED IAW STO-1042WI STRUCTURAL SEAT REPAIR. (K)				
2008FA0000545	CESSNA	PWA	BELLOWS	RUPTURED
7/12/2008	560CESSNA	JT15D5	65550384	
THE BELLOWS INSIDE THE BRADED CONNECTION CRACKED OUT LEAVING A HOLE ABOUT .75 IN IN DIA AT THE UP STREAM SIDE OF THE FLEXIBLE CONNECTOR. THE PROBLEM WAS DISCOVERED ON A MAINT RUN UP AT WHICH TIME THE FIRE DETECTION SYS WAS ACTIVATED FROM AN OVERHEAT SITUATION. RECOMMEND REMOVING THE ELBOWS AND CHECKING THE BELLOWS FOR CRACKS WITH A BORESCOPE. (K)				
CWQR200808	CESSNA		SUPPORT BRACKET	CRACKED
8/21/2008	560XL		661503517	FUSELAGE
DURING A PHASE 1-4 INSP, FOUND THE SUPPORT BRACKET CRACKED, CRACK IS LOCATED IN THE SUPPORT BRACKET FOR THE ECU, THE CRACK INTERSECTS A HOLE FOR THE NUTPLATE THAT ATTACHES ONE OF THE ECU MOUNTING BOLTS. SERVICE CONDITION REPORT HAS BEEN FILED WITH MFG UNDER SCR# 376154.				
2008FA0000560	CESSNA		VALVE	DAMAGED
8/8/2008	R172K		S18271	NOSE STRUT

A NEW VALVE WAS ORDERED AND INSTALLED TO CURE A SUSPECTED LEAK IN THE VALVE CORE. THE NEW VALVE ARRIVED WITH A BRIGHT APPEARANCE, EITHER CHROME OR NICKEL PLATED. WITH THE NEW VALVE INSTALLED, THE STRUT LEAK WORSENER. AN EXTERNAL INSP REVEALED THAT THE COSMETIC PLATING WAS FLAKING FROM THE HEX FLATS. THE VALVE WAS REMOVED AND IT WAS FOUND THAT THE PLATING WAS ALSO FLAKING IN THE THREAD-AREA, AND THIS RESULTED IN A LEAK AROUND THE VALVE. THIS VALVE EMPLOYS A NPT THREAD (1/4 INCH PIPE THREAD) AND THE THREADS FORM THE SEAL WHEN INSTALLED. THE REMAINING PLATING WAS EASILY SCRAPPED FROM THE THREADS WITH A PICK AND THE VALVE WAS REINSTALLED WITHOUT FURTHER DIFFICULTY. SUBMITTER ADMITS THAT THE PLATING RESULTS IN AN ATTRACTIVE PART, HOWEVER THE MFG MAY WISH TO STOP PLATING THE THREADED AREA. (K)

2008FA0000580	CESSNA	PWA	BEARING	FAILED
8/27/2008	S550	JT15D4		STARTER GEN

FRONT BEARING FAILURE IN FLIGHT. (K)

2008FA0000546	CESSNA	CONT	CONTROL CABLE	DEFECTIVE
7/17/2008	T210L	TSIO520*	98600581	TE FLAPS

ORDERED NEW FLAP FOLLOW UP CABLE; TO REPLACED ORIGINAL CABLE WHICH HAD BECOME DEFECTIVE DUE TO NORMAL USAGE AND AGE.

2008FA0000554	CESSNA		INTAKE DUCT	CRACKED
8/13/2008	TU206G		125083029	INDUCTION BOX

MANUFACTURER SUPPLIED ENG INTAKE DUCT BEFORE THE AIR FILTER IS SUBJECT TO CRACKING IN MULTIPLE LOCATIONS. THIS PARTICULAR ACFT AND ANOTHER IDENTICAL MODEL ACFT THIS FACILITY MAINTAINS HAVE BEEN CONVERTED TO AN IO-550-F ENG. AFTER THE STC CONVERSION, THE CRACKING PROBLEM HAS INCREASED SIGNIFICANTLY. CONTACTED THE STC HOLDER AND HAVE RESPONDED WITH A SCHEME TO REINFORCE THIS DUCT. THIS REPAIR STATION IS LOOKING INTO THIS ALTERATION TO THIS DUCT WHICH MAY REQUIRE PER SUPPORT. AT PRESENT, THE DUCTS ARE REQUIRING REPAIRS OR REPLACEMENT EVERY 50 HOURS. A PMA REPLACEMENT DUCT MADE FROM COMPOSITE MATERIAL IS NO LONGER AVAILABLE. (S)

2008FA0000565	CESSNA	CONT	INTAKE DUCT	CRACKED
8/13/2008	TU206G	IO550*	125083029	ENGINE

MFG SUPPLIED ENGINE INTAKE DUCT BEFORE THE AIR FILTER IS SUBJECT TO CRACKING IN MULTIPLE LOCATIONS. THIS PARTICULAR AC AND ANOTHER IDENTICAL MODEL AC THIS FACILITY MAINTAINS, HAVE BEEN CONVERTED TO ANOTHER ENGINE AFTER THE STC CONVERSION. CRACKING PROBLEM HAS INCREASED SIGNIFICANTLY. HAVE CONTACTED STC HOLDER, THEY HAVE RESPONDED WITH A SCHEME TO REINFORCE THIS DUCT. THIS REPAIR STATION IS LOOKING INTO THIS ALTERATION TO THIS DUCT WHICH MAY REQUIRE DER SUPPORT. AT PRESENT, THE DUCTS ARE REQUIRING REPAIRS OF REPLACEMENT EVERY 50 HOURS. A PMA REPLACEMENT DUCT MADE FROM COMPOSITE MATERIAL IS NO LONGER AVAILABLE. (K)

2008FA0000639	CIRRUS	CONT	HINGE	CORRODED
9/2/2008	SR22	IO550*	13431003	TE FLAPS

FLAP HINGES IN ALL POSITIONS BOTH LT AND RT HAVE INTERGRANDULAR CORROSION NEAR THE POINT OF FAILURE. PN 13431-003, PN 13431-004, 13432-002, QTY 2, 13433-006, 13433-005. CONDITION WAS FOUND AT ANNUAL INSPECTION. (K)

IXX2008F00062	DOUG		SKIN	MISREPAIRED
7/9/2008	DC872F			RIGHT WING

DURING ROUTINE C CHECK INSPECTION, FOUND IMPROPER REPAIR RT WING OUTBOARD SLOT VANE LEADING EDGE AT STATION XOLDI 6.224. REMOVED FASTENERS AS NEEDED TO PERFORM REPAIR. REMOVED EXISTING REPAIR. REMOVED DAMAGED AREA. PERFORMED NDT INSPECTION. NO CRACK, NO CORROSION FOUND. FABRICATED REPAIR DOUBLERS, FILLERS, AND INTERNAL DOUBLERS. CLEANED, TREATED AND PRIMED AREA AND REPAIR PARTS. INSTALLED NEW FASTENERS AND REPAIR PARTS AT STATION XOLDI 6.224-XOLDI 67.000 IAW FAA FORM 8110-3 08378 DATED 07/11/2008, SEMAN DRAWING ED-4809 DATED 06/23/08, DC8 SRM 51-1-21, SRM 51-3-0, DC8 NDT SPM PART 06-10-01-001, DC8 SRM 51-1-8B, DC8 SRM 51-1-11, SRM 51-1-20D AND SRM 51-3-1. (S)

IXX2008F00057	DOUG		SKIN	CRACKED
6/16/2008	DC872F			BS 1604-1606

DURING ROUTINE C CHECK INSPECTION, FOUND AFT FUSELAGE EXTERNAL SKIN HAS A CRACK AT STATION 1606.000-1604.000 LONGERON 10 RIGHT. REMOVED FASTENERS AS NEEDED TO PERFORM REPAIR. REMOVED DAMAGED AREA. FABRICATED REPAIR DOUBLER, INTERNAL FINGER DOUBLER, AND FILLER. CLEANED, TREATED AND PRIMED AREA AND REPAIR PARTS. INSTALLED NEW FASTENERS AND REPAIR PARTS IAW DC8 SRM 53-2-1 FIGURE 7 SHEET 1,3, AND 5, SRM 53-5-2 FIGURE 1 ITEM "D", DC8 SRM 51-1-8B, SRM 51-1-11, SRM 51-1-20D, AND SRM 51-3-1. (S)

IXX2008F00063	DOUG	SKIN	CRACKED
6/16/2008	DC872F		BS 1606-1604

DURING ROUTINE C CHECK INSPECTION, FOUND AFT FUSELAGE EXTERNAL SKIN HAS A CRACK AT STATION 1606.000-1604.000 LONGERON 10RT. REMOVED FASTENERS AS NEEDED TO PERFORM REPAIR. REMOVED DAMAGED AREA. FABRICATED REPAIR DOUBLER, INTERNAL FINGER DOUBLER, AND FILLER. CLEANED, TREATED AND PRIMED AREA AND REPAIR PARTS. INSTALLED NEW FASTENERS AND REPAIR PARTS IAW DC8 SRM 53-2-1 FIGURE 7 SHEET 1, 3 AND 5 SRM 53-5-2 FIGURE 1 ITEM "D", DC8 SRM 51-1-8B, SRM 51-1-11, SRM 51-1-21, SRM 51-1-20D, AND SRM 51-3-1. (S)

IXX2008F00064	DOUG	SKIN	DAMAGED
7/9/2008	DC872F		RT WING

DURING ROUTINE C CHECK INSPECTION, FOUND ELONGATED HOLES ON RT WING INBOARD SLOT VANE LEADING EDGE AT STATION XILD 7095.000. REMOVED FASTENERS AS NEEDED TO PERFORM REPAIR. REMOVED DAMAGED PLATING. FABRICATED NEW SKIN. CLEANED, TREATED AND PRIMED AREA AND REPAIR PARTS. INSTALLED NEW FASTENERS AND REPAIR PARTS AT STATION XILD 7095.000-XS 247.000 IAW DC8 SR 57-3-2 FIGURE 10 PAGE 22 ITEM F, DC8 SRM 57-1-0 PAGE 1, SRM 51-1-21, DC8 SRM 51-1-8B, DC8 SRM 51-1-11, SRM 51-3-0 AND SRM 51-3-1. (S)

IXX2008F00060	DOUG	SKIN	MISREPAIRED
6/13/2008	DC872F		RT WING TE FLAP

DURING ROUTINE C CHECK INSPECTION, FOUND RT WING OUTBOARD FLAP PANEL UPPER PART HAS IMPROPER REPAIR AT STATION 360.000. REMOVED FASTENERS AS NEEDED TO PERFORM REPAIR. REMOVED EXISTING REPAIR. FABRICATED NEW SKIN. CLEANED, TREATED AND PRIMED AREA AND REPAIR PART. INSTALLED NEW FASTENERS AND REPAIR PARTS AT STATION XF345.000-360.000 IAW DC8 SRM 57-1-0 PAGE 1, SRM 51-1-21, DC8 SRM 57-7-1 FIGURE 4 ITEM "B" TR 57-94 DATED 10-01-2002, DC8 SRM 51-1-8B, DC8 SRM 51-1-11, SRM 51-3-0, AND SRM 51-3-1. (S)

IXX2008F00069	DOUG	SKIN	CRACKED
6/12/2008	DC872F		BS 188 L27L

DURING ROUTINE C CHECK INSPECTION, FOUND FUSELAGE EXTERNAL PART PRIMARY HEAT EXCHANGER LOWER AFT CORNER CRACKED AT STATION 188.000 LONGERON 27LT. REMOVED FASTENERS AS NEEDED TO PERFORM REPAIR. REMOVED DAMAGED AREA. PERFORMED NDT INSPECTION. NO CRACK, NO CORROSION FOUND. FABRICATED EXTERNAL REPAIR DOUBLER, EXTERNAL REPAIR TRIPLER, AND FILLER. CLEANED, TREATED AND PRIMED AREA AND REPAIR PARTS. INSTALLED NEW FASTENERS AND REPAIR PARTS IAW FAA FORM 8110-3 08378 DATED 7/11/08, SEMAN DRAWING ED4804 DATED 06/23/08, DC8 SRM 51-1-21, SRM 51-3-0, DC8 NDT SPM PART 06-10-01-001, DC8 SRM 51-1-8B, SRM 51-1-11, SRM 51-1-20D, SRM 51-3-0, AND SRM 51-3-1. (S)

IXX2008F00059	DOUG	SKIN	MISREPAIRED
6/14/2008	DC872F		RT WING AILERON

DURING ROUTINE C CHECK INSPECTION, FOUND RT WING OUTBOARD AILERON UPPER SKIN IMPROPER REPAIRS AT STATION XA 630.000-724.000. REMOVED FASTENERS AS NEEDED TO PERFORM REPAIR, REMOVED EXISTING REPAIR. FABRICATED NEW SKIN, DOUBLER. BONDED PARTS AS NEEDED WITH HYSOL. CLEANED, TREATED AND PRIMED AREA AND REPAIR PART. PERFORMED BALANCE, FOUND WITHIN LIMITS MOMENT = 3326.3 IN-LB. INSTALLED NEW FASTENERS AND REPAIR PARTS AT STATION XW 546.000-XA 724.000 IAW DC8 SRM 57-8-1 FIGURE 4 ITEM "F" AND "G", DC8 SRM 57-1-0 PAGE 1, SRM 51-1-21, DOUGLAS DRAWING 5763133, DC8 SRM 51-1-9 TR 51-142, SRM 51-1-9A TR 51-141, DC8 SRM 51-1-8B, IAW DC8 SRM 51-4-3 PAGES 1-6, DC8 SRM 51-1-11, AND SRM 51-1-21. (S)

IXX2008F00028	DOUG	ELEMENT	MALFUNCTIONED
7/17/2008	DC873F		NR 3 NACELLE

FLIGHT NUMBER: 744/ETAR TO OJAM - DESCENDING INTO OJAM NUMBER THREE FIRE WARNING LIGHT AND RED LIGHT IN FIRE HANDLE CAME ON. THE CREW DISCHARGED BOTH BOTTLES AND RED LIGHT IN FIRE HANDLE WAS STILL ON, AND FIRE WARNING WAS INTERMITTENT. THE CREW LANDED IN OJAM WITHOUT FURTHER INCIDENT. MAINTENANCE REPLACED FIRE DETECTOR ELEMENT, LT FAN SENSING ELEMENT, AND BOTH FIRE BOTTLES. OPERATIONAL CHECK GOOD IAW DACO DC8 MAINTENANCE MANUAL 26-10-1, AND 26-20-1. AIRCRAFT WAS RETURNED TO SERVICE. (A)

ABXA080217	DOUG	BATTERY PACK	DISCHARGED
8/12/2008	DC941	60030451	EMERGENCY LIGHT

EMERGENCY LIGHTS INOPERATIVE. REPLACED EMERGENCY LIGHT BATTERY PACK IAW DC9 MM. OPS CHECKED GOOD. (S)

MEW2008F00000	DOUG	PWA	BATTERY PACK	INOPERATIVE
8/6/2008	DC981	JT8D*	B523	EMERGENCY LIGHT

EMERGENCY LIGHTS ABOVE, ON COCKPIT CEILING ARE INOPERATIVE. REMOVED AND REPLACED BATTERY PACK. (K)

MWE2008F00032	DOUG	PWA	WIRE	BROKEN
8/19/2008	DC981	JT8D217C		EMERGENCY LIGHT

EMERGENCY FLOOR LEVEL LIGHTS INOPERATIVE FROM ROW 9 TO 20. REPAIRED BROKEN WIRE IN CENTER SECTION OF LIGHT TRACK. (K)

2008FA0000551	DOUG	BEARING	SEIZED
8/6/2008	MD9030		OIL PUMP

PUMP SEIZED, OIL PUMP BEARING BRACKET SHOWED SIGNS OF RUBBING WITH THE OIL PUMP GEAR. PENDING ENGINEERING EVALUATION. (K)

2008FA0000575	DOUG	SHAFT	SEIZED
8/21/2008	MD9030		AC GENERATOR

GENERATOR UNIT SEIZED. THE GENERATOR FAILURE ROOT CAUSE WAS DETERMINED TO BE A ROTOR BAND SHAFT WHICH RESULTED IN AN OUT OF BALANCE CONDITION. THE OUT OF BALANCE ROOT CAUSED AN EARLY FAILURE OF THE ADE BEARING. ALL OTHER DAMAGE RESULTED FROM THE BEARING FAILURE. PENDING ENGINEERING EVALUATION. (K)

C2XA08IA192	EMB	SIGN	INOPERATIVE
8/10/2008	EMB135LR	7287580503	EMERGENCY LIGHTS

IAH - DURING MAINTENANCE INSPECTION THE MID CABIN CEILING EMERGENCY LIGHT WAS FOUND TO BE INOPERATIVE. MAINTENANCE REMOVED AND REPLACED THE EXIT SIGN. OPERATIONALLY CHECKED WITH NO DEFECTS, AND THE ACFT WAS APPROVED FOR RETURN TO SERVICE. (S)

C2XA08IA191	EMB	INVERTER	INOPERATIVE
8/10/2008	EMB135LR	78241	EMERGENCY LIGHTS

IAH - DURING MAINTENANCE INSPECTION THE FORWARD FLOOR PROXIMITY LIGHT STRIP WAS FOUND TO BE INOPERATIVE. MAINTENANCE REMOVED AND REPLACED THE NR 2 EMERGENCY LIGHT INVERTER, OPERATIONALLY CHECKED WITH NO DEFECTS, AND THE ACFT WAS APPROVED FOR RETURN TO SERVICE. (S)

C2XA08IA182	EMB	BALLAST	BURNED
7/30/2008	EMB145	BR90002	GALLEY

IAH - FLIGHT 2247 - DURING POST FLIGHT INSPECTION THE CREW REPORTED AN ELECTRICAL BURNING SMELL FROM THE GALLEY AREA. MAINTENANCE REMOVED AND REPLACED THE GALLEY LIGHT BALLAST, OPERATIONALLY CHECKED WITH NO DEFECTS, AND THE AIRCRAFT WAS APPROVED FOR RETURN TO SERVICE. (A)

C2XA08IA180	EMB	BALLAST	INOPERATIVE
7/28/2008	EMB145EP	BR90002	CABIN LIGHTS

IAH - FLIGHT 2938 - DURING PRE-FLIGHT INSPECTION, THE CREW REPORTED A BURNING SMELL AT ROW 18. MAINTENANCE INSPECTED THE AIRCRAFT, FOUND A BAD BALLAST AT SEAT 18A. THE BALLAST WAS DISCONNECTED AND THE LIGHT PLACED ON MAL 33-20-00/1 CAT C CONTROL NUMBER 151397 AND THE AIRCRAFT WAS APPROVED FOR RETURN TO SERVICE. ON 08/03/08 MAINTENANCE REMOVED AND REPLACED THE LIGHT BALLAST FOR ROW 18, OPERATIONALLY CHECKED WITH NO DEFECTS, REMOVED THE MEL, AND THE ACFT WAS APPROVED FOR RETURN TO SERVICE. (S)

C2X2008F00014	EMB	BATTERY PACK	INOPERATIVE
7/28/2008	EMB145EP	20131A	EMERGENCY LIGHT

A/C WAS IN FOR A OVERNIGHT SERVICE CHECK AND NR 4 EMERGENCY LIGHT BATTERY WAS FOUND INOP. MAINTENANCE REMOVED AND REPLACED THE NR 4 BATTERY IAW EMB 145 AMM 33-50-04. OPS CHECKS GOOD AND WAS RELEASED BACK TO SERVICE. (A)

C2XA08IA196	EMB	BALLAST	INOPERATIVE
8/25/2008	EMB145LR	78241	EMERGENCY LIGHT

IAH FLIGHT 2312 DURING POST FLIGHT INSPECTION THE GALLEY EXIT LIGHT WAS FOUND TO BE INOPERATIVE. MX R&R THE GALLEY EMERGENCY LIGHT BALLAST, OPS CHECKED WITH NO DEFECTS, AND THE ACFT WAS APPROVED FOR RETURN TO SERVICE.

C2XA08CL097	EMB	MODULE	ODOR
8/24/2008	EMB145LR	7281000501	PSU

CLE FLIGHT NR2173 CREW REPORTED A STRONG ELECTRICAL SMELL NEAR THE MAIN CABIN DOOR. MX INSPECTED AND REPLACED THE PASSENGER SERVICE UNIT CONTROL MODULE OPS CHECKS WERE GOOD.

C2XA08RI115	EMB	INVERTER	INOPERATIVE
8/3/2008	EMB145LR	78241	EMERGENCY LIGHTS

RIC - DURING ROUTINE MAINTENANCE, RIC MX FOUND EMERGENCY LIGHT STRIPS INOPERATIVE. MAINTENANCE REMOVED AND REPLACED EMERGENCY LIGHT INVERTER AND PERFORMED OPERATIONAL CHECK SUCCESSFULLY. ACFT WAS APPROVED TO RETURN TO SERVICE. (S)

C2XA08SH107	EMB	BRACKET	WORN
8/17/2008	EMB145LR	14569009410	RT AILERON

SHV - DURING C-CHECK. THE RT AILERON TO PCA ATTACHMENT BRACKET WAS FOUND TO BE WORN AND WOULD NOT RETAIN THE HAT BUSHINGS. MAINTENANCE REMOVED AND REPLACED THE AFFECTED BRACKET IAW EMB 145 SRM 51-40-02. THE ACFT WAS APPROVED FOR RETURN TO SERVICE. (S)

C2XA08IA177	EMB	MODULE	MALFUNCTIONED
7/24/2008	EMB145LR	2014ABREVC	CABIN PRESSURE

IAH - FLIGHT 2656, THE CREW REPORTED THAT THE CABIN PRESSURIZATION RATE BELOW 20,000 FLUCTUATES WILDLY UP +/- 2500FPM, AND APPEARED TO BE AFFECTED BY THRUST LEVER SETTING. THE AIRCRAFT LANDED AT IAH WITHOUT INCIDENT WHERE MAINTENANCE INSPECTED THE AIRCRAFT AND RESET THE CABIN PRESSURE ACQUISITION MODULE (CPAM), OPERATIONALLY TESTED WITH NO DEFECTS. THE AIRCRAFT WAS APPROVED FOR RETURN TO SERVICE. (A)

C2XA08CL089	EMB	SWITCH	STICKING
7/23/2008	EMB145LR	14563000401	PITCH TRIM

CLE FLIGHT 2018 THE CREW REPORTED A MAIN PITCH TRIM FAIL MESSAGE IN FLIGHT. MAINTENANCE INSPECTED AND FOUND THE FIRST OFFICER'S PITCH TRIM SWITCH WAS STICKING. THE SWITCH WAS REPLACED AND OPERATIONAL CHECKS WERE GOOD. (S)

C2XA08SH108	EMB	BRACKET	WORN
8/17/2008	EMB145LR	14567066401	LT SPOILER

SHV - DURING C-CHECK, THE LT GROUND SPOILER CENTER HINGE BRACKET WAS FOUND TO BE WORN AND WOULD NOT RETAIN THE HAT BUSHINGS. MAINTENANCE REMOVED AND REPLACED THE AFFECTED BRACKET IAW EMB 145 SRM 51-40-02. THE ACFT WAS APPROVED FOR RETURN TO SERVICE. (S)

C2X2008F00020	EMB	PUMP	LEAKING
8/14/2008	EMB145LR		HYDRAULIC SYSTEM

ACFT EN ROUTE FROM EWR TO TYS WHEN THE HYD 1 SYSTEM MESSAGE WAS HYD LOW QUANTITY. MAINTENANCE REMOVED AND REPLACED THE NR 1 ENG DRIVEN HYD PUMP IAW EMB 145AMM 29-10-03 AND REMOVED AND REPLACED THE NR 1 ELECTRIC DRIVEN PUMP IAW EMB 145 AMM 29-10-04. OPS AND LEAK CHECKS WERE GOOD AND WAS RELEASED AFTER A SERVICE ROUTINE WAS COMPLIED WITH. P/N FOR ELECTRIC DRIVEN HYD PUMP (971533, S/N MX683545). (S)

C2XA08SH106	EMB	SILL	CORRODED
8/17/2008	EMB145LR	14525480003	CARGO DOORWAY

SHV - DURING C-CHECK THE CARGO DOOR LOWER SILL CUTOUT WAS FOUND TO BE CORRODED. MAINTENANCE REMOVED AND REPLACED THE LOWER SILL CUTOUT STRUCTURE IAW EMB 145 SRM 51-40-02. THE ACFT WAS APPROVED FOR RETURN TO SERVICE. (S)

C2XA08RI109	EMB	OUTFLOW VALVE	DIRTY
8/10/2008	EMB145LR	2099L011100	CABIN PRESSURE

FLIGHT 3114 - RIC- AIR CREW REPORTED THAT DURING CRUISE, CABIN PRESSURE WAS AT 12,000 FT AT ALTITUDE OF 32,000 FT. FLIGHT WAS DIVERTED TO RIC. CREW LANDED ACFT UNEVENTFULLY. RIC MAINTENANCE CLEANED RT OUTFLOW VALVE AND PERFORMED OPERATIONAL CHECK SUCCESSFULLY. ACFT WAS APPROVED TO RETURN TO SERVICE. (S)

C2XA08IA193	EMB	APU	SMOKE
8/8/2008	EMB145LR		

IAH - FLIGHT 2749 - DURING PRE-FLIGHT THE CREW REPORTED SMOKE IN THE COCKPIT WHEN THE APU WAS STARTED, AND THE CREW SHUT DOWN THE APU. MAINTENANCE INSPECTED ACFT, OPERATIONALLY CHECKED THE APU WITH NO DEFECTS NOTED, AND THE ACFT WAS APPROVED FOR RETURN TO SERVICE. (S)

C2XA08IA179	EMB	INVERTER	INOPERATIVE
7/15/2008	EMB145LR	78241	EMERGENCY LIGHTS

MCI - DURING MAINTENANCE INSPECTION THE SECOND AND THIRD AISLE PATH LIGHT STRIPS WERE FOUND TO BE INOPERATIVE. MAINTENANCE REMOVED AND REPLACED THE NUMBER THREE EMERGENCY LIGHT INVERTER, OPERATIONALLY CHECKED WITH NO DEFECTS AND THE AIRCRAFT WAS APPROVED FOR RETURN TO SERVICE. (A)

C2XAA08IA172	EMB	INVERTER	INOPERATIVE
7/15/2008	EMB145LR	78241	EMERGENCY LIGHTS

IAH - DURING MAINTENANCE INSPECTION THE SECOND AND THIRD EMERGENCY FLOOR LIGHT STRIP WAS FOUND TO BE INOPERATIVE. MAINTENANCE REMOVED AND REPLACED THE NUMBER THREE EMERGENCY LIGHT INVERTER, OPERATIONALLY CHECKED WITH NO DEFECTS, AND THE AIRCRAFT WAS APPROVED FOR RETURN TO SERVICE. (A)

C2XA08SH109	EMB	FLOOR SUPPORT	CORRODED
8/19/2008	EMB145XR	14521700007	FUSELAGE

SHV - DURING C-CHECK LT OMEGA BEAM LOWER FLANGE HAS CORROSION BETWEEN FR 20-24. MAINTENANCE REPAIRED LT OMEGA BEAM LOWER FLANGE BETWEEN FR 20-24 IAW EMB 145 XR SRM 53-00-10 FIGURE 201 SHEET 2. THE ACFT WAS APPROVED FOR RETURN TO SERVICE. (S)

C2XA08SH112	EMB	THRESHOLD	CORRODED
8/19/2008	EMB145XR	14525480603	CARGO DOORWAY

SHV - DURING C-CHECK CARGO DOOR THRESHOLD HAS CORROSION IN MULTIPLE AREAS AROUND AND BOTTOM CUT OUT ANGLE. MAINTENANCE REMOVED AND REPLACED CARGO DOOR THRESHOLD LOWER BEAM IAW EMB 145 XR SRM 51-40-02. THE ACFT WAS APPROVED FOR RETURN TO SERVICE. (S)

C2X2008F00021	EMB	SKIN	PUNCTURED
8/18/2008	EMB145XR		FUSELAGE

EWR/TYS-ACFT WAS STRUCK IN EWR BY A BELTLOADER AND PUNCTURED THE SKIN UNDER THE CARGO BAY. THE ACFT WAS FERRY FLOWN TO TYS. TYS MAINTENANCE INSTALLED A DOUBLER, FILLER, AND SHIMS ON FUSELAGE SKIN BETWEEN FRAMES 64-65 AND STRINGERS 19L-21L IAW EC 5330-01830. THE PRESSURE CHECK WAS GOOD AND THE ACFT WAS RELEASED TO SERVICE. (S)

C2XA08TY089	EMB	BRACKET	GOUGED
8/25/2008	EMB145XR	1456900941050	RT AILERON

A/C WAS IN A C CHECK STATUS AND THE O/B BUSHION HOLE ON THE PCA BRACKET ATTACH POINT WAS FOUND OVERSIZE ON THE RT AILERON. MX REPLACED THE PCA BRACKET IAW EC 5750-01177. ALL WORK WAS ACCOMPLISHED AND WAS RELEASED BACK TO SERVICE.

C2XA08ON167	EMB	SMOKE WARNING	FALSE ACTIVATION
8/9/2008	EMB145XR		CARGO BAY

FLT 0023 - OKC - FLIGHT CREW REPORTED BAGGAGE SMOKE INDICATION ON EICAS. SYSTEM WAS RESET AS PER MAINTENANCE CONTROL INSTRUCTIONS. OPERATIONALLY CHECKED SATISFACTORY AND ACFT WAS RELEASED TO RETURN FOR SERVICE. (S)

C2XA08SH111	EMB	FLOOR SUPPORT	CORRODED
8/19/2008	EMB145XR	14521713005	FUSELAGE

SHV - DURING C-CHECK CENTER OMEGA BEAM FR 18-23 HAS CORROSION. MAINTENANCE REMOVED AND REPLACED CENTER OMEGA BEAM 18-23 IAW EMB 145 XR SRM 51-40-02 AND EC 5320-01140. THE ACFT WAS APPROVED FOR RETURN TO SERVICE. (S)

C2XA08IA187	EMB	CONTROL HANDLE	INOPERATIVE
8/4/2008	EMB145XR	8271013	MLG

IAH-FLIGHT 2352 - THE CREW REPORTED THAT AFTER TAKEOFF THE LANDING GEAR DID NOT INITIALLY RETRACT, AND HAD THE ASSOCIATED DISAGREE MESSAGE ON EICAS. THE ACFT LANDED AT IAH WITHOUT INCIDENT WHERE MAINTENANCE REMOVED AND REPLACED THE LANDING GEAR LEVER. OPERATIONALLY TESTED WITH NO DEFECTS, AND THE ACFT WAS APPROVED FOR RETURN TO SERVICE. (S)

C2XA08IA186	EMB	SOLENOID	INOPERATIVE
8/4/2008	EMB145XR	22250100003	NLG DOORS

IAH-FLIGHT 3044 - THE CREW REPORTED THAT THE NOSE GEAR DOORS WOULD NOT CLOSE. THE ACFT LANDED AT IAH WITHOUT INCIDENT WHERE MAINTENANCE REMOVED AND REPLACED THE NOSE LANDING GEAR DOOR SOLENOID VALVE. OPERATIONALLY TESTED WITH NO DEFECTS, AND THE ACFT WAS APPROVED FOR RETURN TO SERVICE. (S)

COEA0802742	FOKKER	CONNECTOR	DIRTY
7/16/2008	F27MK600		LT ENG OIL IND

RETURN TO BLOCKS. FLT 8777. ON TAXI TO THE RUNWAY THE LT ENGINE OIL PRESSURE GAGE DROPPED TO AN INDICATION OF "0". THE LT ENGINE WAS SHUT DOWN AND THE A/C TAXIED SAFELY BACK TO THE RAMP. DISCONNECTED CONNECTORS AT THE OIL PRESSURE GAGE AND OIL PRESSURE TRANSMITTER FOR THE LT ENGINE. CLEANED CONNECTIONS AND RECONNECTED REMOVED CONNECTORS. SYSTEM CHECK AND ENGINE RUN FOUND SYSTEM OPERATION NORMAL. (A)

EHS2008F00000	GULSTM	LYC	PISTON	BURNED
7/2/2008	500S	IO540E1B5		NR 3 CYLINDER

WHILE FLYING A FIRE MISSION IN SUPPORT OF USFS, THE PILOT NOTICED THE RT ENG OIL PRESSURE FLOWLY STARTING TO DECREASE. THE DECISION WAS MADE TO RETURN TO THE AIRPORT. AS OIL PRESSURE CONTINUED TO DECREASE, THE DECISION WAS MADE TO SHUTDOWN, FEATHER, AND SECURE THE ENG. A SAFE LANDING WAS ACCOMPLISHED AND THE ACFT WAS TAKEN OUT OF SERVICE. UPON INSPECTION, IT WAS FOUND THAT THE NR 3 CYLINDER'S PISTON RINGS AND RING GROOVES WERE DAMAGED, WHICH PRESSURIZED THE CASE AND PUMPED THE ENG OIL OVERBOARD. THE ENG WAS REMOVED AND SENT FOR OVERHAUL AS A PRECAUTION. PROBABLE CAUSE: POSSIBLE BROKEN RING OR POSSIBLE DETONATION. (S)

WWQ2008F0000	GULSTM	RROYCE	TRANSCEIVER	SHORTED
3				
8/2/2008	G1159	SPEY*	MI5853511	WX RADAR

AC WAS DISPATCHED, THE CREW CAPTAIN AND F/O DEPARTED AT 13:40 ENROUTE. AT APPROX 13:50, WHILE CLIMBING OUT OF 8000 FEET, PILOTS NOTICED THE RADAR SCREEN START TO FLICKER. CAPT IMMEDIATELY SHUT THE RADAR OFF. A SHORT WHILE LATER PILOTS SMELLED WHAT APPEARED TO BE SMOKE RELATED TO ELECTRICAL FIRE. PILOTS THEN SAW HEAVY SMOKE COMING OUT OF THE DASHBOARD. CAPT THEN DECLARED AN EMERGENCY, INITIALLY REQUESTED TO DIVERT, DUE TO THE AVAILABILITY OF LONGER RUNWAYS AND MUCH BETTER EMERGENCY EQUIPMENT IN CASE IT WAS NEEDED. AFTER PERFORMING CORRECT CHECKLIST AND ASSESSING THE SITUATION THE SMOKE HAD DISSIPATED AND CAPT DECIDED THAT THERE WAS NO LONGER AN EMERGENCY. AT THAT POINT REQUESTED TO FLY BACK TO DEPARTURE AND LANDED AT 14:05 WITH NO ADDITIONAL PROBLEMS. INSPECTED COCKPIT AND DETERMINED THE WEATHER RADAR CONTROL UNIT (CRT) HAD SHORTED OUT INTERNALLY. INSPECTED BEHIND THE INSTRUMENT PANEL AND ASSOCIATED WIRING GOING TO THE WEATHER RADAR CONTROL UNIT (CRT) AND NO DEFECTS NOTED. REMOVED THE BAD CRT AND INSTALLED INSPECTED CRT, PERFORMED OPS CHECKS OF THE SYS. ALL OPERATIONAL CHECK GOOD WITH NO DEFECT NOTED. (K)

2008FA0000572	GULSTM	GARRTT	ACTUATOR	LEAKING
8/18/2008	G159	TFE7314R	35380000000	RT MLG

RT MLG SIDE BRACE ACTUATOR LEAKING FROM SWITCH ASSY. SIDE BRACE ACTUATOR REMOVED, REPLACED WITH REPAIRED ACTUATOR ASSY.

WWQ2008F0000	GULSTM	RROYCE	GEAR	WORN
2				
8/1/2008	GIV	TAY6118	YU10352	RT STARTER

RT ENGINE FAILED TO START, FOUND THAT THE STARTER WAS BAD. DURING THE STARTER REPLACEMENT, NOTICED ABNORMAL WEAR ON THE ENGINE GEAR BOX STARTER GEAR. CONTACTED ENGINEERING DEPARTMENTS TO AS FOR LIMITATIONS. AFTER ENGINEERING DEPARTMENTS REVIEWED PICTURES, THEY DETERMINED THAT THE STARTER GEAR BOX GEAR REQUIRED FURTHER EVALUATIONS. SPECIAL FLIGHT PERMIT (FERRY FLIGHT) AND FLEW THE AC FOR FURTHER EVALUATION. ENGINEERS DETERMINED STARTER GEAR IN THE GEAR BOX REQUIRED REPLACEMENT. A RENTAL ENGINE IS BEING INSTALLED AND ENGINE SN 16257 GEAR BOX STARTER WILL BE REPLACED. (K)

K2D2008F00000	HUGHES		PRESSURE SWITCH	LEAKING
8/6/2008	369E		369H81445	ENG FUEL PUMP

ON OR AROUND 5:00 PM, WEDNESDAY, 6 AUGUST, 2008, WHILE CONDUCTING A POST FLIGHT INSP, DISCOVERED SOME OIL LEAKAGE IN ENGINE COMPARTMENT. AS HE WAS INVESTIGATING LEAKAGE, NOTICED THAT THE FUEL FILTER PRESSURE SWITCH HAD PLAYED BETWEEN TWO BODY HALVES AND HAD SOME FUEL LEAKAGE. AT WHICH TIME, GROUNDED HELICOPTER, RESCHEDULED OUR FLIGHTS FOR NEXT DAY, AND ORDERED THE PART TO REPAIR THE FAULT. AT THIS TIME, HAVE NO PROBABLE CAUSE FOR THIS INCIDENT BUT DID INFORM THE MECHANIC TO USE CAUTION IN TORQUING THE LINES AND FITTINGS THAT CONNECT THIS PART TO THE ENGINE. (K)

FOM2008F00000	LEAR	GARRTT	DOWNLOCK SWITCH	INTERMITTENT
8/9/2008	35A	TFE731*	P624007	MLG

ON FINAL APPROACH, DURING PART 91 FLIGHT FOR AC OWNER, CREW NOTED THA THE LT MLG WOULD NOT INDICATE REQUIRED "GREEN" DOWN-LOCK INDICATION. ALL OTHER GEAR INDICATED PROPERLY AFTER NORMAL EXTENSION. CREW PROCEEDED WITH EMERGENCY CHECKLIST ITEMS IAW MFG, INCLUDING EMERGENCY GEAR EXTENSION PROCEDURE, AND NO CHANGE IN SITUATION OCCURRED. LT MLG STILL DID NOT INDICATE DOWNLOCKED. CREW CONDUCTED SEVERAL FLY-BY MANEUVERS TO HAVE ATC CONTROL TOWER VERIFY GEAR POSITION. ATC REPORTED "GEAR APPEARS DOWN AND LOCKED". CREW COMPLETED ALL EMERGENCY CHECKLIST ITEMS AND BRIEFED OCCUPANTS ON UPCOMING "GEAR UNSAFE" LANDING. CREW DECLARED EMERGENCY AND PROCEEDED WITH APPROACH AND LANDING AT AIRPORT WITHOUT INCIDENT. GEAR HELD AND LANDING WAS UNEVENTFUL. THE FOLLOWING DAY (8/10/2008) CREW POWERED UP AC AND NOW DID NOTE PROPER GREEN DOWN LOCK INDICATION ON LT MAIN GEAR. FERRY PERMIT WAS OBTAINED AND AC WAS FERRIED. UPON INSPECTION AT MAINT FACILITY, REPORT NOTED THAT " DOWNLOCK INDICATOR SWITCH" LOCATED ON LT MAIN GEAR ACTUATOR WAS FAULTY. COMPONENT WAS REPLACED WITH NEW COMPONENT AND SYSTEM WAS SERVICED. AC WAS RETURNED TO SERVICE ON OR ABOUT 08/13/2008. ALL OPS CHECKS WERE NORMAL. PART IS ON CONDITION WITHOUT TBO/LIFE LIMIT REQUIREMENTS, ON CONDITION ONLY. NON SERIALIZED PART/COMPONENT. (K)

2008FA0000556	LEAR		TRANSDUCER	MALFUNCTIONED
7/2/2008	60LEAR		1240583000	HYD PRESSURE

HYDRAULIC PRESSURE GAUGE READ ZERO ON LANDING CHECK. FLAPS AND LANDING GEAR EXTENDED NORMALLY. GAUGE WAS SEEN TO FLUCTUATE BETWEEN NORMAL TO 1000 PSI TO ZERO PSI ON APPROACH. BRAKES AND THRUST REVERSERS OPERATED NORMALLY. GAUGE READS ZERO DURING TAXI. CREW DECLARED AN IFE AS A PRECAUTION. MAINTENANCE REPLACED THE HYDRAULIC PRESSURE TRANSDUCER. OPS CHECK AND LEAK CHECK PERFORMED SATISFACTORILY. (S)

2008FA0000547	MOONEY	LYC	DOWNLOCK	WORN
6/28/2008	M20B	O360A1A	560006	MLG

LANDING GEAR LEVER BECAME DISENGAGED FROM THE DOWNLOCK LATCHING ASSY ON THE PILOT'S LOWER CENTER INSTRUMENT PANEL. AC WAS ON THE GROUND DURING LANDING ROLLOUT. THIS ALLOWED GEAR TO COLLAPSE, SB M20-88B, 5-10-94. (K)

2008FA0000571	MTSBSI		CONTROL CABLE	BROKEN
7/22/2008	MU2B36A			ELEVATOR

PILOT COMPLAINED OF POOR ELEVATOR TRIM OPS. UPON INSP, FOUND ELEVATOR TRIM CABLE 311AS-14-7245 BROKEN (RT CABLE). 311AS-14-7362 (LT CABLE), 010A-61179-81 (RT AFT) CABLES FRAYED. IDLER PULLEY SHAFT ON PITCH TRIM SERVO SHEARED. REPLACED CABLES & SERVO, OPS CHECKED. RIGGED AS NEEDED.

2008FA0000559	PIPER	LYC	DRIVE SHAFT	BROKEN
8/10/2008	PA28R200	IO360C1C		MAGNETO

DISTRIBUTOR (POINT CAM SHAFT BROKE FLUSH WITH UPPER MAG GEAR INNER RACE CAUSING TOTAL MAG FAILURE. PART WAS RETURNED TO OWNER. (K)

NTB2008F00001	PIPER	CONT	SPRING	BROKEN
8/8/2008	PA28R201T	TSIO360F		IMPULSE COUPLING

IMPULSE COUPLING SPRING BROKEN. EVIDENCE OF PRE-EXISTING CRACK AND CORROSION. VERY LOW TIME IS SERVICE. MAG TO ENGINE TIMING LOST. BOTH MAGS EXPERIENCED THE SAME FAILURE ALMOST SIMULTANEOUSLY. (K)

2008FA0000579	PIPER	LYC	RESERVOIR	LOW
6/10/2008	PA31325	LTIO540F2BD		HYD SYSTEM

ON FINAL APPROACH THE LANDING GEAR HANDLE WAS PLACED IN THE DOWN POSITION. THE GEAR WAS VIEWED IN THE MIRROR AT 45 DEGREE ANGLE. THERE WERE NO GREEN LIGHTS INDICATING GEAR DOWN AND LOCKED. THE PILOT TRIED TO RAISE AND LOWER THE GEAR AGAIN WITH NO MOVEMENT EITHER DIRECTION. THE PILOT THEN PROCEEDED TO MANUALLY PUMP THE GEAR DOWN. AFTER THREE GREEN LIGHTS WERE ON, THE AIRCRAFT WAS FLOWN BACK, WITH THE GEAR DOWN. MAINT NOTE: HYDR RESERVOIR WAS FOUND TO BE IMPROPERLY SERVICED. TRAINING WAS CONDUCTED FOR ALL MAINT ON PROPERLY SERVICING THE POWERPACK. THIS CAN BE TRICKY AS IT IS DIFFICULT TO SEE THE FLUID LEVEL. (K)

2008FA0000549	PIPER	LYC	DOUBLER	CRACKED
8/4/2008	PA32R301T	TIO540*	99813004	FUSELAGE

UPPER COMM/NAV ANTENNA DOUBLER AND SKIN CRACKED FROM FWD SEAM ALONG BOTH ANTENNA MOUNT NUTPLATE LINES. CRACKS ARE APPROX 6 INCHES LONG WITH ADDITIONAL CRACKING RADIATING OUT FROM FWD NUTPLATES TO FWD DOUBLER MOUNTING RIVETS. ANTENNA DOUBLER IS CRACKED COMPLETELY THROUGH ON LT SIDE AND 90 PERCENT THROUGH ON RT SIDE. DAMAGE PICTURE AVAILABLE UPON REQUEST. DAMAGE APPEARS TO HAVE BEEN CAUSED BY PROLONGED OIL CANNING OF THE UPPER SKIN PANEL FROM AERODYNAMIC LOADS AGAINST THE ANTENNA DURING FLIGHT. TO PREVENT REOCCURRENCE REPAIR WITH FLUSH PATCH IAW 43.13-1B, SEC 4, HOWEVER BEND .5 INCH LIP ON LT, RT AND AFT EDGES OF BACKING PATCH TO INCREASE STIFFNESS AND REDUCE OIL CANNING EFFECT. JOG FRONT EDGE OF BACKING PATCH AND TIE INTO FWD SKIN SEAM/RIB AND EXTEND LT, RT AND AFT EDGES 4 INCHES PAST REMOVED DAMAGE AREA. AN ALTERNATE REPAIR WOULD BE TO REPLACE THE ENTIRE AFFECTED SKIN SECTION AND REMANUFACTURE ANTENNA DOUBLER TO TIE INTO THE FWD AND AFT RIBS TO STIFFEN THE ENTIRE AREA. (K)

2008FA0000548	PIPER	LYC	SKIN	CRACKED
8/4/2008	PA32R301T	TIO540*	69904000	FUSELAGE

UPPER COMM/NAV ANTENNA DOUBLER AND SKIN CRACKED FROM FWD SEAM ALONG BOTH ANTENNA MOUNT NUTPLATE LINES. CRACKS ARE APPROX 6 INCHES LONG WITH ADDITIONAL CRACKING RADIATING OUT FROM FWD NUTPLATES TO FWD DOUBLER MOUNTING RIVETS. ANTENNA DOUBLER IS CRACKED COMPLETELY THROUGH ON LT SIDE AND 90 PERCENT THROUGH ON RT SIDE. DAMAGE PICTURE AVAILABLE UPON REQUEST. DAMAGE APPEARS TO HAVE BEEN CAUSED BY PROLONGED OIL CANNING OF THE UPPER SKIN PANEL FROM AERODYNAMIC LOADS AGAINST THE ANTENNA DURING FLIGHT. TO PREVENT REOCCURRENCE REPAIR WITH FLUSH PATCH IAW 43.13-1B, SEC 4, HOWEVER BEND .5 INCH LIP ON LT, RT AND AFT EDGES OF BACKING PATCH TO INCREASE STIFFNESS AND REDUCE OIL CANNING EFFECT. JOG FRONT EDGE OF BACKING PATCH AND TIE INTO FORWARD SKIN SEAM/RIB AND EXTEND LT, RT AND AFT EDGES 4 INCHES PAST REMOVED DAMAGE AREA. AN ALTERNATE REPAIR WOULD BE TO REPLACE THE ENTIRE AFFECTED SKIN SECTION AND REMANUFACTURE THE ANTENNA DOUBLER TO TIE INTO THE FORWARD AND AFT RIBS TO STIFFEN THE ENTIRE AREA. (K)

2008FA0000561	PIPER	LYC	WIRE	BROKEN
5/13/2008	PA44180	O320*		ALTERNATOR

INTERNAL FAILURE DUE TO BROKEN WIRES INTERNALLY, HEAVY SPARKING INSIDE ENGINE COMPARTMENT. (K)

2008FA0000573	RAYTHN		FLOAT VALVE	SEPARATED
8/21/2008	390		1183810025	FUEL TANK

DURING 1200 HR INSP WHICH REQUIRES OPENING ALL WING AND FUSELAGE FUEL TANK ACCESS PANELS FOR INTERNAL INSPECTION IN BOTH LT & RT CTR FUSELAGE TANKS, FWD FLOAT VENT VALVES FLOAT SECTION OF VALVE ASSY WAS FOUND SEPARATED AND LAYING LOOSE INSIDE FUEL TANK AREA. RECOMMEND INSP OF LT & RT FWD VENT VALVE FLOAT ASSEMBLIES AT NEXT EARLIEST TIME OR INSP. REPLACE ALL SUSPECTED OR FAULTY FLOAT VALVES.

2008FA0000552	RAYTHN		LINE	RUPTURED
5/21/2008	HAWKER800X P		SA7670024001	HYD SYSTEM

HYDR FLEXIBLE LINE TO RT MLG DOOR ACTUATOR RUPTURED DURING FLIGHT. LOSS OF FLUID CAVITATED RT AND LT ENGINE DRIVE HYDR PUMPS. LINE RUPTURED IN SIDEWALL NEAR SWAGED END FITTING FOR CONNECTOR. PRESSURE IS 3000 PSI CONSTANT. NO LANDING GEAR ACTUATION WAS IN PROCESS. SUSPECT MFG DEFECT. AC MFG NOTIFIED. THIS IS FIRST INSTANCE OF THIS FOR THS AC. LT MLG DOOR HYDR LINE RUPTURED 2 MONTHS BEFORE IN THE SAME EXACT WAY AND CAUSED THE SAME DAMAGE. MFG NOTIFIED AGAIN.

2008FA0000553	RAYTHN		LINE	RUPTURED
8/8/2008	HAWKER800X P		SA7670024001	HYD SYSTEM

HYDR FLEXIBLE LINE TO THE LT LANDING GEAR DOOR ACTUATOR RUPTURED DURING FLIGHT. LOSS OF FLUID CAVITATED LT AND RT ENG DRIVEN HYDR PUMPS. LINE RUPTURED IN SIDEWALL NEAR SWAGED END FITTING FOR CONNECTOR. PRESSURE IS 3000 PSI CONSTANT. NO LANDING GEAR ACTUATION WAS IN PROCESS. SUSPECT MFG DEFECT. AC MFG NOTIFIED. THIS IS SECOND OCCURRENCE FOR THIS AC. SAME LINE RUPTURED 2 MONTH PREVIOUSLY ON RT SIDE ACTURATOR CAUSING SAME DAMAGE. MFG AGAIN NOTIFIED. (K)

DJF2008F00013	RAYTHN		UNKNOWN	SMOKE
8/25/2008	HAWKER800X P			CABIN

THE A/C TAXIED IN AND CHALKED AS ENGINES WERE BEING SHUT DOWN. THE COCKPIT AND CABIN STARTED FILLING WITH SMOKE. THE CREW REPORTED THE SMOKE CLEARED AFTER ALL ELECTRICAL AND ENGINE AND APU WERE SHUT DOWN. OPEN

2008FA0000541	RAYTHN	GARRTT	MODULE	FAILED
8/1/2008	HAWKER800X P	TFE7315BR	30753507	LPT

AIRCRAFT EXPERIENCED A VIBRATION IN FLIGHT. CREW SHUTDOWN NR 1 ENGINE AND LANDED. MAINT CREWS DETERMINED THE THIRD STAGE LOW PRESSURE TURBINE (LPT) MODULE HAD EXPERIENCED A BLADE FAILURE. ONE BLADE WAS MISSING A PIECE ABOUT ONE INCH LONG. MAINT ALSO DISCOVERED A CRACK IN THE THIRD STAGE STATOR WHICH EXTENDED BETWEEN ONE THIRD TO ONE HALF THE CIRCUMFERENCE OF THE HOUSING. NO OTHER ANOMALIES WERE NOTED DURING THE DISASSEMBLY OF THE ENGINE. PARTS WERE SENT TO MFG FOR INVESTIGATION AND REPAIR. (K)

DGC2008F00001	RKWELL	GARRTT	PUMP	INOPERATIVE
8/18/2008	NA26565	TFE7313R1D	PF24390615BCES 62	HYD SYSTEM

ON AUGUST 16, 2008, AT APPROXIMATELY 8:30 AM, AFTER LANDING, THE CREW HEARD AUDIBLE WARNING OF HYDRAULIC SYSTEM LOW PRESSURE. THE AC TAXIED TO THE RAMP OF DESTINATION, WITHOUT INCIDENT. UPON INVESTIGATION, THE HYDRAULIC PUMP WAS FOUND TO HAVE FAILED. (K)

PNS2008F00008	SAAB	GE	SOCKET	BURNED
8/14/2008	340B	CT79B	BVO33000250	CABIN LIGHT

WHILE ENROUTE, FLIGHT CREW WAS NOTIFIED BY THE F/A THAT THERE WAS SMOKE AND AN ODOR IN THE CABIN, THE FLIGHT CREW PERFORMED EMERGENCY PROCEDURES AND AN UNEVENTFUL LANDING WAS MADE AT THE DESTINATION AIRPORT. MAINT FOUND THE OVERHEAD LIGHT FIXTURE ABOVE SEAT 1A WAS BURNED AND MELTED. THE SYSTEM WAS DEFERED AND THE AC RETURNED TO THE MAINT BASE AND THE LAMP HOLDER WAS REPLACED AND THE LIGHTING SYS TESTED. WE HAVE HAD SIMILAR ISSUES WITH THESE LAMP HOLDERS WHICH ARE MADE OUT OF PLASTIC. IT WOULD BE BETTER IF THESE LAMP HOLDERS WERE MADE FROM CERAMIC OR ANOTHER MATERIAL THAT WOULD RESIST MELTING AND BURNING. (K)

2008FA0000550	SCWZER	ALLSN	DRIVE SHAFT	UNSERVICEABLE
7/29/2008	269D	250C20	269D53085	MAIN ROTOR

DURING PREFLIGHT, THE M/R DROOP STOP NUT WAS FOUND TO BE LOOSE. UPON FURTHER INSP IT WAS DETERMINED THAT M/R HUB SHOULD BE REMOVED TO LOOK FOR SIGNS OF WEAR. ONCE HUB WAS REMOVED AND INSPECTED, MODERATE WEAR (FRETTING) WAS FOUND ON DROOP STOP RETAINER PLATE (PN 269A1320), DROOP STOP RETAINER RING (PN 269D1329), DROOP STOP RETAINER (PN 269A1332) AND UPPER SCISSORS SUPPORT (PN 269A1328-901) TO THRUST BEARING TUBE SPACER ASSY (PN 269A13183). ONCE THESE PARTS WERE REMOVED, THE DRIVE SHAFT WAS REMOVED FOR INSP. ONCE DRIVE SHAFT WAS REMOVED THE DRIVE SHAFT THRUST BRG WAS REMOVED FOR INSP AND CORROSION WAS FOUND ON DRIVE SHAFT THRUST BRG JOURNAL. CORROSION WAS REMOVED AND FURTHER VISUAL EXAMINATION REVEALED A POSSIBLE CRACK THAT WAS LOCATED RADIALY ALONG THE JOURNALS SURFACE. DYE PENETRANT OF SUSPECT AREA WAS PERFORMED WHICH REVEALED A .375 INCH ANOMALY. DRIVE SHAFT WAS THEN SENT TO AN OUTSIDE NDT FACILITY WHERE A MAG PARTICLE INSP WAS PERFORMED VERIFYING THE ANOMALY. NEXT, AN EDDY CURRENT TEST WAS PERFORMED THAT PROVED THE ANOMALY WAS ALSO BELOW THE SURFACE WITH APPROXIMATELY .005 INCH OF SEPARATION. PART WAS RETURNED TO MFG FOR FURTHER EXAMINATION AND EVALUATION. (K)

2008FA0000570	SNIAS	TMECA	BEARING	WORN
7/29/2008	AS350BA	ARRIEL1	704A33651158	M/R SWASHPLATE

COMPLIED WITH 2 YEAR / 500 HR INSP. TASK 62.30.00.601 M/R SHAFT INSP. WHILE PERFORMING INSP OF SWASHPLATE GUIDE UNIBALL FOUND WHILE ROTATING SWASHPLATE. UPPER SEAL FOR BRG WAS NOT ROTATING BECAUSE IT WAS NOT FIRMLY ATTACHED TO OUTER RACE OF BRG WITH THE SEAL BEING LOOSE & UNSECURED IT WORE INTO SWASHPLATE BRG OUTER STOP RING. REPLACED SWASHPLATE BRG, OUTER STOP RING WITH NEW. RECOMMENDATION WOULD BE WHILE GREASING SWASHPLATE BRG DURING 100 HOUR INSP, LIFT SWASHPLATE BOOT TO INSPECT BRG SEAL FOR MOVEMENT DURING ROTATION. (L)

2008FA0000544	SOCATA	LYC	ALTERNATOR	FAILED
7/30/2008	TB9	O320D2A	ALU8521	ENGINE

ALTERNATOR WILL FAIL ABOVE 2500 RPM, LOW VOLTAGE LIGHT COMES ON AND THE VOLTMETER INDICATES BATTERY VOLTAGE. OPS CHECK DURING GROUND RUNS ARE NORMAL MAX RPM DURING GROUND RUN 2400 RPM. ALTERNATOR APPEARS TO BE RPM SENSITIVE. POSSIBLE CAUSE: BRUSHES NOT RIDING TRUE ON SLIP RING. OVERHAUL PROCESS MAY CONTRIBUTE TO PROBLEM. AN ADDITIONAN (2) ALU8521 ALTERNATORS FROM INVENTORY PRODUCE THE SAME SYMPTOMS, SN E113128 AND F043304. BOTH ALTERNATORS FAILED WITHIN 2 HOURS OF OPERATION. BOTH WERE O/H UNITS. (K)

